




IG4000 Universal Replacement Kit

Kit content




Safe Installation Procedure

1. Disconnect electrical power and gas supply to appliance or furnace and remove HSI igniter.
2. Cut the 2 wires of the burnt-out igniter 3-4 inches from ceramic block.
3. Compare the old ceramic block with the new parts in kit and select the appropriate metal bracket to best match the original igniter. See drawings shown below.
4. Connect existing wires to the new igniter and use the 2 ceramic wire nuts to complete the connection. Ensure that the 2 wire nuts are tightly secured for proper electrical connection.
5. Re-install the new igniter in the reverse order of removal.
6. Test the appliance or furnace several times for proper ignition.

Warranty is for burnt out only

DO NOT USE THIS IGNITER FOR ANY OTHER APPLICATION

Original ⇒ *Replacement*



Amana 10735002	Icp/Heil/ Arco Air	Rheem Rudd 62-22868-93	Norton 101M
Arco Air See ICP	Comfortmaker	62-22441-01	201D
Armstrong 38322B001	Tempstar	62-22868-82	201K
Clare Bros. C238 C238-1	Keeprite	Roberts-Gordon 90434300	201L 201M
Coleman/Evcon 14740511 14740512	109604 1096047 1096048 1009604	90436600	201P
Detroit/ Brant Radiant 201D	Integra 6905032 3260618	Superior Fireplace 94851	201W 271D 271M
DMO/Olsen ECR Ind. 26789 20834	Johnstone L37-699 L37-700 L37-812	Trane 3400339P01	271N 271NM 271P 271R 271RS 271W
Dornback 271W	Johnstone L37-814 L37-815 L37-816	B340039P01 B12996P01 B144676P01 B144676P02	Robertshaw/ Uniline 41-238 41-242 41-402 41-403 41-404
Ducane 20015201	L.B. White Co 120-07549	IGN21 IGN23 IGN26 IGN28 IGN30 IGN34	41-405 41-407 41-408 41-409 41-410 41-412 41-414 41-1090
Enerco Tech. 10399	Lennox 33J3701	Viessmann 9302-093 9302-094	41-405 41-407 41-408
Goodman/Janitrol B1172606 B1193939 B1401009 B1401015 B1401018	Majestic 75-92-104 75-92-105	Wayne Home Equipment 62821-001 62821-002	41-409 41-410 41-412 41-414
John Woods/ GSW P.V. 86483	Metzger 201N 201W	Weil McLain 29074	White -RodgersS 767A-301 767A-303 767A-306 767A-310 767A-311 767A-315 767A-350 767A-353 767A-354 767A-357 767A-361 767A-364 767A-365 767A-366 767A-370 767A-371 767A-372
H.B. Smith 50018	Mor-Flo 3200618	511-330-139 511-330-193	767A-301 767A-303 767A-306 767A-310
Hupp Ind 9050	Nordyne/Tappan Frigidaire/Philco Intertherm/Miller 903110	511-330-190 Williamson 09050	767A-310 767A-311 767A-315
Raypak 600915	105141000 RH622286893 632-0770 632-0880 902661 902694 903758 632-3811 632-3540	025-32626-000 473-12509-001 373-09154-700 025-27774-000 025-29043-000 025-29050-000 025-27766-000 025-30277-000 025-32638-002 025-32625-000 025-31801-000 373-05342-700	767A-353 767A-354 767A-357 767A-361 767A-364 767A-365 767A-366 767A-370 767A-371 767A-372

Sealed Unit Parts Co., Inc.

2230 Landmark Place
Allenwood, NJ 08720 USA
Phone: 732-223-6644 • Fax: 732-223-1617
www.supco.com • info@supco.com