

# Universal Recorder Charts

KTP RANGE 1	KTP RANGE 2	12 HR	24 HR	7 DAY	31 DAY
-20°F to 120°F	0-50 PSI	<b>CRTP2-1</b>			
-20°F to 120°F	0-150 PSI		<b>CRTP2-11</b>	<b>CRTP2-38</b>	
-20°F to 120°F	0-500 PSI	<b>CRTP2-3</b>	<b>CRTP2-12</b>	<b>CRTP2-39</b>	
-20°F to 50°F	0-50 PSI	<b>CRTP2-4</b>	<b>CRTP2-13</b>	<b>CRTP2-40</b>	<b>CRTP2-58</b>
-20°F to 50°F	0-150 PSI	<b>CRTP2-5</b>	<b>CRTP2-14</b>	<b>CRTP2-41</b>	<b>CRTP2-59</b>
-20°F to 50°F	0-500 PSI	<b>CRTP2-6</b>	<b>CRTP2-15</b>	<b>CRTP2-42</b>	<b>CRTP2-60</b>
40°F to 110°F	0-50 PSI	<b>CRTP2-7</b>	<b>CRTP2-16</b>	<b>CRTP2-43</b>	<b>CRTP2-61</b>
40°F to 110°F	0-150 PSI	<b>CRTP2-8</b>	<b>CRTP2-17</b>	<b>CRTP2-44</b>	<b>CRTP2-62</b>
40°F to 110°F	0-500 PSI	<b>CRTP2-9</b>	<b>CRTP2-18</b>	<b>CRTP2-45</b>	<b>CRTP2-63</b>
-30°C to 50°C	0-3.5 BAR	<b>CRTP2-19</b>	<b>CRTP2-28</b>	<b>CRTP2-46</b>	<b>CRTP2-64</b>
-30°C to 50°C	0-10 BAR	<b>CRTP2-20</b>	<b>CRTP2-29</b>	<b>CRTP2-47</b>	<b>CRTP2-65</b>
-30°C to 50°C	0-35 BAR		<b>CRTP2-30</b>	<b>CRTP2-48</b>	<b>CRTP2-66</b>
-30°C to 10°C	0-3.5 BAR	<b>CRTP2-22</b>	<b>CRTP2-31</b>	<b>CRTP2-49</b>	<b>CRTP2-67</b>
-30°C to 10°C	0-10 BAR	<b>CRTP2-23</b>	<b>CRTP2-32</b>	<b>CRTP2-50</b>	<b>CRTP2-68</b>
-30°C to 10°C	0-35 BAR	<b>CRTP2-24</b>	<b>CRTP2-33</b>	<b>CRTP2-51</b>	<b>CRTP2-69</b>
5°C to 45°C	0-3.5 BAR	<b>CRTP2-25</b>	<b>CRTP2-34</b>	<b>CRTP2-52</b>	<b>CRTP2-70</b>
5°C to 45°C	0-10 BAR	<b>CRTP2-26</b>	<b>CRTP2-35</b>	<b>CRTP2-53</b>	<b>CRTP2-71</b>
5°C to 45°C	0-35 BAR	<b>CRTP2-27</b>	<b>CRTP2-36</b>	<b>CRTP2-54</b>	<b>CRTP2-72</b>